



October 22, 2015

Subject: New BAE Systems Facility Fort Wayne, Indiana

Dear Valued Customer,

The relocation of the BAE Systems Fort Wayne Repair Station (GZFR112K) is almost complete. This re-location to a new facility is approximately five miles from the current site and is located within one mile of the airport. After November 2, 2015, please begin shipping product for repair to the new address listed below. Any product shipped to the previous location at 2000 Taylor Street will be forwarded to the new address for an overlap period. However your assistance in making this shipping change on November 2, will support in not extending turn times. The new address is:

- BAE Systems Controls Inc
Repair Station
4250 Airport Expressway
Fort Wayne, Indiana USA 46809

The Repair Station number, personnel, equipment, and procedures are unchanged from the previous site.

If you have any questions or would like to discuss in further detail, please contact your BAE Systems Customer Service Representative. As always our goal is to provide customers with the best possible solutions, the highest quality, fastest responsiveness, and best value.



David Weber
Aftermarket Program Manager
Fort Wayne, Indiana
+1-260-434-5199